# Three-Year Asbestos Hazard Emergency Response Act Re-Inspection and Management Plan Update

for

Forestdale School

For Compliance with

Commonwealth of Massachusetts Department of Labor Standards (MADLS)
Asbestos Containing Materials in Schools Regulation (453 CMR 6.00)

and

EPA Asbestos Hazard Emergency Response Act (Title 40 CFR Part 763, Subpart E)

#### Sandwich Public School District

Sandwich, Massachusetts

March 2017



Fuss & O'Neill EnviroScience, LLC 50 Redfield Street, Suite 100 Boston, MA 02122



March 2, 2017

Mr. Jonathan Nelson Facilities and Grounds Sandwich Public School District 33 Water Street Sandwich, MA 02563

RE: Three-Year AHERA Re-Inspection and Management Plan Update Forestdale School 151 Route 130, Sandwich, MA

Fuss & O'Neill EnviroScience, LLC No. 20160762.A1E

Dear Mr. Nelson:

Enclosed is the Three-Year AHERA Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill EnviroScience, LLC for the Forestdale School located at 151 Route 130 in Sandwich, Massachusetts. AHERA services were performed for Sandwich Public School District (the "Client").

This report is an important document that must be kept on file at the school, as well as at a central location where the Asbestos Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

50 Redfield Street Suite 100 Boston, MA 02122 t 617.282.4675

> 800.286.2469 f 617.282.8253

Dustin A. Diedricksen Senior Project Manager

DD/so

Enclosure

www.fando.com

Connecticut
Massachusetts
Rhode Island
South Carolina



#### **Table of Contents**

#### Three-Year Asbestos Hazard Emergency Response Act Re-Inspection and Management Plan Update Forestdale School

1	Introd	luction	1
	1.1	Background	1
	1.2	Local Education Agency (LEA) Responsibilities	1
	1.3	Key Personnel	2
2	Buildi	ng and Mechanical System Description	3
3	Three	Year Re-Inspection	3
	3.1	Re-Inspection Procedures	
4	Re-In:	spection Report	4
	4.1	Existing Records Review	
	4.2	Re-Inspection Summary	4
	4.3	Newly-Identified or Re-Sampled ACBM	7
	4.4	ACBM Physical Assessment	7
5	Mana	ngement Plan Update	7
	5.1	Recommended Response Actions	
	5.2	Periodic Surveillance	8
	5.3	Preventive Measures	8
6	EPA A	Accreditation Requirements	9
Appe	ndices	End o	of Report
APPE	NDIX A	EXISTING RECORDS CHECKLIST	
APPE	NDIX B	ASBESTOS LABORATORY ANALYTICAL RESULTS AND CHAIN	I-OF-
		CUSTODY FORM	
APPE	NDIX C	2012 RE-INSPECTION ASBESTOS LABORATORY RESULTS	
APPE	NDIX D	SAFETY DATA SHEETS	
APPE	NDIX E	ENVIROSCIENCE STATE CERTIFICATIONS AND EPA	
		ACCREDITATIONS	



#### 1 Introduction

#### 1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations require that local education agencies (LEA) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988, which is to be used as a school building, shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for a private or public school system, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the Commonwealth of Massachusetts, the Department of Labor Standards (MADLS) is responsible for AHERA regulation enforcement.

# 1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
  - 1. The LEA must designate a person to ensure that all AHERA requirements are properly implemented. The LEA's Designated Person must receive adequate training to perform their duties.
  - 2. The LEA must ensure that the Asbestos Management Plans (AMP) are maintained in a central location as well as at each facility; these AMP and pertinent documentation shall be available for inspection or review at all times.
  - 3. The LEA must inform all workers, building occupants, and legal representatives (as appropriate) in writing at least once per school year about asbestos-related activities and the availability of the AMP for each school building.



- 4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, AMP development/updates, Asbestos Work Plan (AWP) development, and response actions that may disturb asbestos; this includes operations and maintenance (O&M) activities.
- 5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, and refresher training must be completed annually.
- The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
- 7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
- 8. The LEA must ensure that periodic surveillance is performed at least once every six months, after AMP implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
- 9. The LEA must ensure that once every three years, after an AMP is implemented, a reinspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

#### 1.3 Key Personnel

A. Local Education Agency (LEA)

LEA: Sandwich Public School District

Address: 33 Water Street

Sandwich, Massachusetts 02563

Phone: (508) 888-1054

B. Designated Mr. Jonathan Nelson

Person: Head of Facilities and Grounds

Address: 33 Water Street

Sandwich, Massachusetts 02563

Phone: (508) 888-3312



#### C. Asbestos Consultant Data

Firm: Fuss & O'Neill EnviroScience, LLC

Address: 50 Redfield Street, Suite 100

Boston, MA 02122

Phone: (617)-282-4675 Fax: (617)-282-8253

#### D. Asbestos Inspector

Inspector: Robert Mallett MADLS Certification Number: AI900557 Expiration Date: 06/01/2017

E. Asbestos Management Planner:

Planner: Dustin Diedricksen

MADLS Certification Number: AP900425 Expiration Date: 04/05/2017

# 2 Building and Mechanical System Description

The Forestdale School is a two-story building reportedly constructed in 1989; portable classrooms were reportedly added in 1999.

Two Weil-McLain gas-fired, hot-water boilers provide heat to the building. Hot water is transferred via a closed-loop system through the ceiling plenum to unit ventilators throughout the building.

### 3 Three Year Re-Inspection

#### 3.1 Re-Inspection Procedures

This Three-Year AHERA Re-Inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On December 28, 2016, Mr. Robert Mallett of Fuss & O'Neill EnviroScience, LLC (EnviroScience) performed the re-inspection.

- A. During the re-inspection, EnviroScience conducted the following required tasks:
  - 1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
  - 2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.



3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

#### 4 Re-Inspection Report

#### 4.1 Existing Records Review

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where AMP are stored.

Please see *Appendix A* for the checklist for existing records.

#### 4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the MADLS.

Eighteen bulk samples were collected during this re-inspection. The results can be found in Table 1. Refer to *Appendix B* for a copy of the asbestos laboratory analytical results and chain-of-custody form.

Bulk samples were last collected during the 2012 re-inspection. The results can be found in Table 1. Refer to *Appendix C* for a copy of the 2012 re-inspection asbestos laboratory results.

Using EPA protocol and criteria, none of the materials existing in the building at the time of this three-year re-inspection have been determined or assumed to be **ACBM**.

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

Table 1
Non-Asbestos-Containing Building Materials

Homogeneous Material	Location(s)	Reference & Sample Number
Joint Compound	Original Building, 1 <sup>st</sup> & 2 <sup>nd</sup> Floor Classrooms, Hallways, Offices, & Storage Rooms	AMP July 2012 Prepared by Cardno ATC. (Sample IDs 01A-01G)
Gypsum Wallboard	Original Building, 1 <sup>st</sup> & 2 <sup>nd</sup> Floor Classrooms, Hallways, Offices, & Storage Rooms	AMP July 2012 Prepared by Cardno ATC. (Sample IDs 02A & 02B)



Homogeneous Material	Location(s)	Reference &				
Wateriai		Sample Number AMP				
	Opinia al Davildina 1st 9- 2nd					
2' x 2' Ceiling Tile	Original Building, 1 <sup>st</sup> & 2 <sup>nd</sup> Floor Classrooms	July 2012 Prepared by Cardno ATC.				
	Floor Classrooms	(Sample IDs 03A & 03B)				
		-				
X/ 11 - Mr. (* A . * , 1 . * )	Original Building, 1st & 2nd	AMP				
Yellow Mastic Associated with	Floor Classrooms, Hallways,	July 2012				
Black Cove Base	Offices, & Storage Rooms	Prepared by Cardno ATC.				
	_	(Sample IDs 04A & 04B)				
	O : 1 D : 11 0 4 2 0 2 d	AMP				
Gray Sink Coat	Original Building & 1st & 2nd	July 2012				
,	Floor Classrooms	Prepared by Cardno ATC.				
		(Sample IDs 05A & 05B)				
		AMP				
Black Sink Coat	Original Building & 1st & 2nd	July 2012				
	Floor Classrooms	Prepared by Cardno ATC.				
		(Sample IDs 06A & 06B)				
		AMP				
12" x 12" White Mottled Floor Tile	Original Building, 1st & 2nd	July 2012				
12 X 12 Winte Motted 1 Roof The	Floor Hallways & Classrooms	Prepared by Cardno ATC.				
		(Sample IDs 07A & 07B)				
		AMP				
Black Mastic Associated with 12" x	Original Building, 1st & 2nd	July 2012				
12" Floor Tile	Floor Hallways & Classrooms	Prepared by Cardno ATC.				
		(Sample IDs 08A & 08B)				
		AMP				
Yellow Mastic Associated with	Original Building & 1st & 2nd	July 2012				
Gray Carpet	Floor Classrooms	Prepared by Cardno ATC.				
		(Sample IDs 09A & 09B)				
		AMP				
Community To a	Classes 210 8 220	July 2012				
Counter Top	Classrooms 210 & 220	Prepared by Cardno ATC.				
		(Sample IDs 11A & 11B)				
		AMP				
Black Side Light & Partition Wall	Original Building & 2nd Floor	July 2012				
Window Glazing Compound	Lobby	Prepared by Cardno ATC.				
	_	(Sample IDs 12A & 12B)				
		AMP				
0) 4) 1971 17	Portable Classrooms:	January 2017				
2' x 4' White Fissure & Dot	Classrooms, Bathrooms, &	Prepared by EnviroScience				
Suspended Ceiling Tile	Hallway	(Sample IDs 01A & 01B-				
	ĺ	RCM-1228)				



Homogeneous	Location(s)	Reference &
Material	.,	Sample Number
6" Gray Vinyl Baseboard	Portable Classrooms: Classrooms, Bathrooms, & Hallway	AMP January 2017 Prepared by EnviroScience (Sample IDs 02A & 02B- RCM-1228)
Yellow Adhesive Associated with 6" Vinyl Baseboard	Portable Classrooms: Classrooms, Bathrooms, & Hallway	AMP January 2017 Prepared by EnviroScience (Sample IDs 03A & 03B- RCM-1228)
Gray Gypsum Wallboard	Portable Classrooms: Classrooms, Bathrooms, & Hallway	AMP January 2017 Prepared by EnviroScience (Sample IDs 04A & 04B- RCM-1228)
12" x 12" White with Blue Splotch Floor Tile	Portable Classrooms: Bathrooms, & Hallway	AMP January 2017 Prepared by EnviroScience (Sample IDs 05A & 05B- RCM-1228)
Black Mastic Associated with 12" x 12" Floor Tile	Portable Classrooms: Bathrooms, & Hallway	AMP January 2017 Prepared by EnviroScience (Sample IDs 06A & 06B- RCM-1228)
Yellow Carpet Glue	Portable Classrooms: Classrooms	AMP January 2017 Prepared by EnviroScience (Sample IDs 07A & 07B- RCM-1228)
1' x 1' White Fissure & Dot Ceiling Tile (Glued)	Classroom 112	AMP January 2017 Prepared by EnviroScience (Sample IDs 08A & 08B- RCM-1228)
Brown Glue Daub Associated with 1' x 1' White Fissure & Dot Ceiling Tile	Classroom 112	AMP January 2017 Prepared by EnviroScience (Sample IDs 09A & 09B- RCM-1228)

AMP = AHERA Management Plan



Mr. Dustin Diedricksen reviewed the information obtained during this re-inspection. Mr. Diedricksen is an EPA-accredited and MADLS-Certified Asbestos Management Planner.

# 4.3 Newly-Identified or Re-Sampled ACBM

Nine new suspect ACBMs were identified during this re-inspection.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air. In accordance with EPA National Emission Standards for Hazardous Air Pollutants (NESHAP), samples of these and other exterior suspect ACM must be collected and analyzed for asbestos content prior to disturbance.

Safety Data Sheets (SDS) must be obtained and kept with the AHERA documentation for any newly-installed materials in order to meet AHERA requirements. These SDS must demonstrate that asbestos-containing materials were not installed in the building. We recommend that SDS for newly-installed materials be inserted into *Appendix D*.

#### 4.4 ACBM Physical Assessment

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as linoleum, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Based on bulk sample results and building construction date, the Forestdale School has been determined not to contain ACBM at the time of this three-year re-inspection. Therefore, physical assessments were not required.

## 5 Management Plan Update

#### 5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

- 1. Removal Not Applicable
- 2. Repair Not Applicable



- 3. Enclosure Not Applicable
- 4. Encapsulation Not Applicable
- 5. O & M Not Applicable

#### 5.2 Periodic Surveillance

At least once every six months after a management plan is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school where ACBM have been identified in the AMP, record the date of surveillance, their name, and any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Based on bulk sample results and building construction date, the Forestdale School has been determined not to contain ACBM at the time of this three-year re-inspection. Therefore, six month periodic surveillance is not required.

Safety Data Sheets (SDS) must be obtained and kept with the AHERA documentation for any newly-installed materials in order to meet AHERA requirements. These SDS must demonstrate that asbestoscontaining materials were not installed in the building.

#### 5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated or delaminated.

Based on bulk sample results and building construction date, the Forestdale School has been determined not to contain ACBM at the time of this three-year re-inspection Therefore, preventative measures in regards to ACBM are not required.

Safety Data Sheets (SDS) must be obtained and kept with the AHERA documentation for any newly-installed materials in order to meet AHERA requirements. These SDS must demonstrate that asbestoscontaining materials were not installed in the building.



# **6 EPA Accreditation Requirements**

The MADLS certifications and EPA accreditations for the individuals (Mr. Dustin Diedricksen and Mr. Robert Mallett) involved in performing the re-inspection and updating the AMP are provided in *Appendix E*.

Report prepared by Environmental Technician, Robert Mallett.

Reviewed by:

Dustin A. Diedricksen Senior Project Manager



# Appendix A

**Existing Records Checklist** 



#### **Existing Records Checklist**

Local Education Agency (LEA): Sandwich Public School District

33 Water Street

Sandwich, MA 02563

School Building: Forestdale School

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year re-inspection.

	Daarmaadakian	Location				
	Documentation	LEA Office	School			
1.	Original AHERA Inspection/Management Plan	No	No			
2.	Three Year Re-Inspections	2012, 2015	2012, 2015			
3.	Notifications to Parents/Guardians and Teachers (yearly since last re-inspection)	No	No			
4.	Designated Person Identified and Proper Training (person must be named and have appropriate training)	Yes	Yes			
5.	Designated Person Periodic Surveillance (every six months since last re-inspection)	N/A	N/A			
6.	Record of Awareness Training for Maintenance Staff	Yes	Yes			
7.	Outside Vendor Awareness Notification	No	No			
8.	Warning Signs and Labels (required posting in Boiler room and mechanical spaces only)	N/A	N/A			
9.	Record of Response Actions (includes any abatement done since last re-inspection)	N/A	N/A			

Comments: <u>Items marked "No" indicate not present/available at the time of this inspection.</u>

Inspector (LEA Office): Robert Mallett Date: December 28, 2016

Inspector (School): Robert Mallett Date: December 28, 2016



# Appendix B

Asbestos Laboratory Analytical Results and Chain-of-Custody Form



EMSL Order: 131700084 Customer ID: ENVI54

Customer PO: 20160762.A1E-15

Project ID:

Attention: Dustin Diedricksen Phone: (617) 778-3750

Fuss & O'Neill EnviroScience, LLC Fax: (888) 838-1160

146 Hartford Road Received Date: 12/30/2016 9:17 AM

Manchester, CT 06040

Analysis Date: 01/09/2017

Collected Date: 12/28/2016

Project: 20160762.A1E Task 15 / Sandwich Public Schools, 3-Yr AHERA Re-Inspections / Forestdale School - 151

Route 130, Sandwich, MA

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			stos	<u>Asbestos</u>			
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type		
01A-RCM-1228 131700084-0001	Portable Classrooms, Hallway - 2'x4' White Fissure & Dot Suspended Ceiling Tile	Gray/White Fibrous Homogeneous	60% Cellulose 20% Min. Wool	20% Non-fibrous (Other)	None Detected		
01B-RCM-1228 131700084-0002	Portable Classrooms, Hallway - 2'x4' White Fissure & Dot Suspended Ceiling Tile	Gray/White Fibrous Homogeneous	60% Cellulose 20% Min. Wool	20% Non-fibrous (Other)	None Detected		
02A-RCM-1228 131700084-0003	Portable Classrooms, Hallway - 6" Gray Vinyl Baseboard	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
02B-RCM-1228 131700084-0004	Portable Classrooms, Hallway - 6" Gray Vinyl Baseboard	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
03A-RCM-1228 131700084-0005	Portable Classrooms, Hallway - Yellow Adhesive Associated with 6" Vinyl Baseboard	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
03B-RCM-1228 131700084-0006	Portable Classrooms, Hallway - Yellow Adhesive Associated with 6" Vinyl Baseboard	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
04A-RCM-1228 131700084-0007	Portable Classrooms, Hallway - Gray Gypsum Wallboard	Brown/White Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected		
04B-RCM-1228 131700084-0008	Portable Classrooms, Hallway - Gray Gypsum Wallboard	Brown/White Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected		
05A-RCM-1228 131700084-0009	Portable Classrooms, Hallway - 12"x12" White with Blue Splotch Floor Tile	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
05B-RCM-1228 131700084-0010	Portable Classrooms, Hallway - 12"x12" White with Blue Splotch Floor Tile	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
06A-RCM-1228 131700084-0011	Portable Classrooms, Hallway - Black Mastic Associated with 12"x12" Floor Tile	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		
06B-RCM-1228 131700084-0012	Portable Classrooms, Hallway - Black Mastic Associated with 12"x12" Floor Tile	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected		

Initial report from: 01/09/2017 14:26:44



**EMSL Order:** 131700084 **Customer ID:** ENVI54

Customer PO: 20160762.A1E-15

Project ID:

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
07A-RCM-1228 131700084-0013	Portable Classrooms, Classroom 1 - Yellow Carpet Glue	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
07B-RCM-1228 131700084-0014	Portable Classrooms, Classroom 2 - Yellow Carpet Glue	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
08A-RCM-1228 131700084-0015	Classroom 112 - 1'x1' White Fissure & Dot Glued Ceiling Tile	Gray/White Fibrous Homogeneous	60% Cellulose 20% Min. Wool	20% Non-fibrous (Other)	None Detected
08B-RCM-1228 131700084-0016	Classroom 112 - 1'x1' White Fissure & Dot Glued Ceiling Tile	Gray/White Fibrous Homogeneous	60% Cellulose 20% Min. Wool	20% Non-fibrous (Other)	None Detected
09A-RCM-1228 131700084-0017	Classroom 112 - Brown Glue Daub Associated with 1'x1' Ceiling Tile	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
09B-RCM-1228 131700084-0018	Classroom 112 - Brown Glue Daub Associated with 1'x1' Ceiling Tile	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)

Michael Mink (18)

Steve Grise, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3, VT AL998919, Maine Bulk Asbestos BA039

Initial report from: 01/09/2017 14:26:44

# 131700084



EMSL Customer No. ENVI54

www.fando.com


50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

	Asbestos Bulk	Sample Chain-of	-Custody	Sheet of				
Project Name:	Sandwich Public Schools, 3-Yr AHERA F	Re-Inspections	Project No.: 2016076	2.A1E Task: 15				
Building Name/Numb	per: Forestdale School		Project Manager:	D Diedricksen				
Site Address:	151 Route 130,u Sandwich, MA		Total # of Samples: _	18				
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample 1	Comments/ Quantities					
01A-RCM-1228	2' x 4' White Fissure & Dot Suspended Ceiling Tile	Portable Classr	rooms, Hallway					
01B-RCM-1228	2' x 4' White Fissure & Dot Suspended Ceiling Tile	Portable Classr	ooms, Hallway					
02A-RCM-1228	6" Gray Vinyl Baseboard	Portable Classr	rooms, Hallway					
02B-RCM-1228	6" Gray Vinyl Baseboard	Portable Classr	rooms, Hallway					
03A-RCM-1228	Yellow Adhesive Associated with 6" Vinyl Baseboard	Portable Classr	rooms, Hallway					
03B-RCM-1228	Yellow Adhesive Associated with 6" Vinyl Baseboard	Portable Classr	rooms, Hallway	8				
04A-RCM-1228	Gray Gypsum Wallboard	Portable Classr	ooms, Hallway					
04B-RCM-1228	Gray Gypsum Wallboard	Portable Classr						
05A-RCM-1228	12" x 12" White with Blue Splotch Floor Tile	Portable Classr	ooms, Hallway					
05B-RCM-1228	12" x 12" White with Blue Splotch Floor Tile	Portable Classrooms, Hallway						
06A-RCM-1228	Black Mastic Associated with 12" x 12" Floor Tile	Portable Classrooms, Hallway						
06B-RCM-1228	Black Mastic Associated with 12" x 12" Floor Tile	Portable Classrooms, Hallway						
07A-RCM-1228	Yellow Carpet Glue	Portable Classroo						
07B-RCM-1228	Yellow Carpet Glue	Portable Classroo	oms, Classroom 2					
08A-RCM-1228	1' x 1' White Fissure & Dot Glued Ceiling Tile	Classro	om 112					
08B-RCM-1228	1' x 1' White Fissure & Dot Glued Ceiling Tile	. Classroo	om 112					
09A-RCM-1228	Brown Glue Daub Associated with 1' x 1' Ceiling Tile	Classroo	om 112					
09B-RCM-1228	Brown Glue Daub Associated with 1' x 1' Ceiling Tile	Classro	om 112	91				
Analysis Method: 🛛 PL	M   TEM   Other		Turnaround Tin	ne:1-week				
Please call EnviroScience a	at (617) 282-4675 if analyses will not be compl	eted for requested turnaro	und time listed above.					
Email Results to:do	diedricksen & Rmallett @fando.com	Do Not Mail Hard (	Copy Report FAX Re	sults to: 888-838-1160.				
Special Instructions: Stop	p analysis on first positive sample in each hom	ogeneous set of samples u	intess otherwise noted. De	o not layer samples				
unless indicated. Do not po Samples Collected by:	001/14	DEC 3 0 2016	Date: 12/2	* //L				
campies conceted by:	e e e e e e e e e e e e e e e e e e e	ey 68 9:17	7 7952 1920	5 1570				

Page 1 Of 2 \_ ISL Fx

OrderID: 131700084



# 131700084

EMSL Customer No. ENVI54

www.fando.com

50 Redfield Street, Suite 100, Boston	n, MA 02122		Phone (617) 282-4675	Fax (617) 282-8253
Samples Sent by:	200	Date: 12/29/k	Time: PM	
Shipped To: ⊠ EMSL MA	☐ Other			
<b>Method of Shipment:</b> $\boxtimes$ Fed Ex	☐ Lab Drop Off	Other		





# **Appendix C**

2012 Re-Inspection Asbestos Laboratory Results

Client Name:

ATC Associates, Inc., Woburn

PO #: Client Project #: N/A

N/A

Client Reference: Forestdale School Method: EPA/600/R-93/116 Batch:

B82058

Date Sampled:

N/A

Date Received: Date Analyzed: 7/5/2012 7/6/2012

Date of Report:

7/10/2012

		Asbestos %							Non-Asbestos %						
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON	
01A	White	0	0	0	0	0	0	0	0	0	0	0	0	100	

Description: Location:

Joint compound

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		Asbestos %							Non-Asbestos %					
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
01B	White	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Location:

Joint compound

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		Asbestos %					Non-Asbestos %							
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	WNW	CEL	HAR	SYN	OTH	NON
01C	White	0	0	0	0	0	0	0	0	0	0	0	0	100
	•••••													

Description: Location:

Joint compound Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		Lister).		Asbes	stos %	, Maria C				Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
01D	White	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Joint compound

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

A CONTRACTOR OF THE PROPERTY O		(AND A	74 ( ) ( )	Asbes	tos %	adalah l				Non-	Asbest	os %		
	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
Sample ID	White	0	0	0	0	0	0	0	0	0	0	0	0	100
01E	11111111								•					

Description: Joint compound

Location: Comments: Throughout

Is asbestos present? No.

Analyzed: Yes

		03.05		Asbes	tos %		THE STATE			Non-	-Asbesto	os %		
	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
Sample to	White	0	0	0	0	0	0	0	0	0	0	0	0	100
01F	AALIIC													

Description: Location: Comments:

Joint compound

Throughout

Is asbestos present? No.

Client Name:

ATC Associates, Inc., Woburn

PO#: Client Project #: N/A

Client Reference: Forestdale School Method: EPA/600/R-93/116 Batch:

B82058

Date Sampled:

N/A

Date Received: Date Analyzed: 7/5/2012 7/6/2012

Date of Report:

7/10/2012

Samula ID				Asbes	stos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
01G	White	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Joint compound

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

Samuel In		Service.	Elevitor	Asbes	stos %	Galler T.				Non-	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
02A	Multi	0	0	0	0	0	0	TR	0	5	0	0	0	95

Description:

Gypsum board Location:

Comments:

Throughout

Is asbestos present? No.-

Analyzed: Yes

_				Asbes	stos %	(Migray)	CITY IN			Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
02B	Multi	0	0	0	0	0	0	TR	0	2	0	0	0	98

Location:

Description: Gypsum board Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		ALC: N	WANACE.	Asbes	stos %					Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
03A	Multi	0	0	0	0	0	0	0	20	60	0	0	0	20

Description: 2'x2' Ceiling tile

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

				Asbes	stos %					Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
03B	Multi	0	0	0	0	0	0	0	20	60	0	0	0	20

Description: 2'x2' Ceiling tile

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		all states		Asbes	stos %	Kalaba				Non	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
04A	Yellow	0	0	0	0	0	0	0	0	0	0	0	0	100

Description:

Yellow mastic assoc. w/black CB

Location:

Throughout

Comments:

Is asbestos present? No.

Client Name:

ATC Associates, Inc., Woburn

PO#:

N/A

Client Project #: N/A

Client Reference: Forestdale School

Method:

EPA/600/R-93/116

Batch:

B82058

Date Sampled:

N/A

Date Received:

7/5/2012 7/6/2012

Date Analyzed: Date of Report:

7/10/2012

		Child Co	NW. A	Asbes	tos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
04B	Yellow	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Yellow mastic assoc. w/black CB

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		MARKET		Asbes	stos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
05A	Gray	0	0	0	0	0	0	0	0	25	0	0	0	75

Description:

Gray sink coat

Location:

Room 116

Comments:

Is asbestos present? No.

Analyzed: Yes

				Asbes	stos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
05B	Gray	0	0	0	0	0	0	0	0	25	0	0	0	75

Description: Gray sink coat

Location:

Room 116

Comments:

Is asbestos present? No.

Analyzed: Yes

		QUEST!		Asbes	tos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
06A	Black	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Black sink coat

Location:

Room 235

Comments:

Is asbestos present? No.

Analyzed: Yes

and the second second second		DAMES NO.		Asbes	itos %		SAME TO			Non-	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
06B	Black	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Black sink coat

Location:

Room 228A

Comments:

Is asbestos present? No.

Analyzed: Yes

		CHANN'S	SHATT	Asbes	tos %					Non-	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
07A	White	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: 12"x12" White floor tile

Location:

Throughout

Comments:

Is asbestos present? No.

Client Name:

ATC Associates, Inc., Woburn

PO#: Client Project #:

N/A

N/A

Client Reference: Forestdale School EPA/600/R-93/116 Method:

Batch:

B82058

Date Sampled: Date Received:

N/A 7/5/2012

Date Analyzed:

7/6/2012

Date of Report:

7/10/2012

		1111		Asbes	tos %					Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
07B	White	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: 12"x12" White floor tile

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

				Asbes	stos %					Non-	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
08A	Black	0	0	0	0	0	0	0	0	10	0	0	0	90

Description:

Black mastic assoc. w/white FT

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		WO (See	vigues (a)	Asbes	tos %					Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
08B	Black	0	0	0	0	0	0	0	0	10	0	0	0	90

Description: Black mastic assoc. w/white FT

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

		Liumes.		Asbes	tos %	11	34/374			Non-	Asbesto	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
09A	Yellow	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Yellow mastic assoc. w/gray carpet

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

			M. Metal	Asbes	tos %			Tarre Charle		Non-	Asbesto	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
09B	Yellow	0	0	0	0	0	0	0	0	0	0	0	0	100

Description:

Yellow mastic assoc. w/gray carpet

Location:

Throughout

Comments:

Is asbestos present? No.

Analyzed: Yes

Sample ID Color CHR ANO CRO ACT TRE ART TBS MINT SEE TAX STA			8433		Asbes	stos %					Non	Asbest	os %		
Sample ID	OIn ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
10A Gray 0 0 0 0 0 0 0 1 0 1 0 1 0 1 0 1 0 1 0		Gray	0	0	0	0	0	0	0	0	0	0	0	0	100

Description:

Gray leveling compound

Location: Comments: Classroom

Is asbestos present? No.

Client Name:

ATC Associates, Inc., Woburn

PO#: Client Project #: N/A

N/A

Client Reference: Forestdale School

Method:

EPA/600/R-93/116

Batch:

B82058

Date Sampled:

N/A

Date Received: Date Analyzed: 7/5/2012

Date of Report:

7/6/2012 7/10/2012

		41,447	Thus year	Asbes	tos %	weight.	r dalah			Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
10B	Gray	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Gray leveling compound

Location:

Comments:

Classroom

Is asbestos present? No.

Analyzed: Yes

		1711.143		Asbes	stos %	Markets				Non-	Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON
11A	Black	0	0	0	0	0	0	0	0	0	0	0	0	100

Description: Counter top

Location:

Room 210

Comments:

Is asbestos present? No.

Analyzed: Yes

		10/40-41		Asbes	tos %					Non	-Asbest	os %		
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON
11B	Black	0	0	0	0	0	0	0	0	5	0	0	0	95

Description:

Counter top

Location:

Room 220

Comments:

Is asbestos present? No.

Analyzed: Yes

		Asbestos %							Non-Asbestos %								
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	ОТН	NON			
12A	Black	0	0	0	0	0	0	0	0	5	0	0	0	95			

Description: Black caulk

Location:

Side light window

Comments:

Is asbestos present? No.

Analyzed: Yes

			Asbestos %								Non-Asbestos %							
	Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON			
AND STATE		Black	0	0	0	0	0	0	0	0	5	0	0	0	95			
	12B	Black		U				السنسا						J	`			

Description: Black caulk

Location:

Side light window

Comments:

Is asbestos present? No.

Analyzed: Yes

		Asbestos %							Non-Asbestos %						
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON	
13A	White	5	0	0	0	0	0	0	0	0	0	0	0	95	

Description: White caulk

Location: Comments:

Exterior window

Is asbestos present? Yes.

Client Name:

ATC Associates, Inc., Woburn

PO#:

Client Project #: N/A

Client Reference: Forestdale School EPA/600/R-93/116 Batch:

Date Sampled:

B82058 N/A

Date Received:

Date Analyzed:

7/5/2012

Date of Report:

7/6/2012 7/10/2012

2		Asbestos %							Non-Asbestos %						
Sample ID	Color	CHR	AMO	CRO	ACT	TRE	ANT	FBG	MNW	CEL	HAR	SYN	OTH	NON	
13B		0	0	0	0	0	0	0	0	0	0	0	0	0	
Description: White caulk															

Location:

Comments:

Exterior window

Analyzed: No

Asbestos Codes: Non-Asbestos Codes:

CHR = Chrysotile FBG = FiberglassNote: To create a unique lab sample ID, use the Batch # and the Sample ID (example: [Batch #] - [Sa

AMO = Amosite MNW = Mineral Wool

CRO = Crocidolite CEL = Cellulose

ACT = Actinolite HAR = Hair

TRE = Tremolite SYN = Synthetic

OTH = Other

ANT = Anthophyllite
H = Other NON = Non-Fibrous Minerals

\* All results are in percentage.

Analyst: Dan Pine


Page 6 of 6



# **Appendix D**

Newly-Installed Materials Safety Data Sheets

To be Provided by LEA



#### Commonwealth of Massachusetts

Department of Labor Standards

William D. McKinney, Director

**Asbestos Inspector** 

#### **ROBERT C. MALLETT**

Eff. Date 05/10/16 Exp. Date 06/01/17

Al900557

Member of C.O.N.E.S.

BOSR









# Robert C Mallett



has completed the requisite training, and has passed an examination for reaccreditation as:

# Asbestos Inspector Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Institute for Environmental Education, Inc. 16 Upton Drive Wilmington, MA 01887 Course Location

January 7, 2016

Course Dates

16-0243-106-400644

Certificate Number

January 07, 2016

**Examination Date** 

January 07, 2017

**Expiration Date** 

**Training Director** 

16 Upton Drive, Wilmington, MA 01887 Telephone 978,658,5272

www.leetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION

#### Commonwealth of Massachusetts

Department of Labor Standards

William D. McKinney, Director

#### **Asbestos Management Planner**

#### **DUSTIN A. DIEDRICKSEN**

Eff. Date 04/05/16 Exp. Date 04/05/17

AP900425

Member of C.O.N.E.S.

**BOS-RENEW** 











has completed the requisite training, and has passed an examination for

**Dustin A. Diedricksen** 

reaccreditation

Asbestos Management Planner Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Institute for Environmental Education, Inc. 16 Upton Drive Wilmington, MA 01887 Course Location

January 21, 2016

Course Dates

16-0267-136-208040

Certificate Number

January 21, 2016

**Examination Date** 

January 21, 2017

**Expiration Date** 

Training Director

Telephone 978,658,5272 16 Upton Drive, Wilmington, MA 01887

www.eetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION